Package 'mistat'

October 13, 2022

Type Package

Title Data Sets, Functions and Examples from the Book: ``Modern Industrial Statistics'' by Kenett, Zacks and Amberti

Version 2.0.3

Date 2021-04-18

Author Daniele Amberti

Depends R (>= 3.5)

Imports graphics, grDevices, methods, stats, utils

Suggests e1071, mvtnorm, AcceptanceSampling, boot, car, Dodge, tseries, qcc, DoE.base, FrF2, rsm, LearnBayes, ggplot2, grid, DiceEval, DiceKriging, DiceDesign, DiceView, lhs, survival, rpart, fdapace, randomForest, xgboost

Maintainer Daniele Amberti <daniele.amberti@gmail.com>

Description Provide all the data sets and statistical analysis applications used in ``Modern Industrial Statistics: with applications in R, MINITAB and JMP'' by R.S. Kenett and S. Zacks with contributions by D. Amberti, John Wiley and Sons, 2021, which is a third revised and expanded revision of ``Modern Industrial Statistics: Design and Control of Quality and Reliability'', R. Kenett and S. Zacks, Duxbury/Wadsworth Publishing, 1998.

License GPL (>= 2)

RoxygenNote 6.0.1

NeedsCompilation no

Repository CRAN

Date/Publication 2021-04-18 13:20:03 UTC

R topics documented:

---

mistat-package   *The Modern Industrial Statistics Package*

Description

This R package is providing all the data sets and statistical analysis of *Modern Industrial Statistics, with applications using R, MINITAB and JMP* by R.S. Kenett and S. Zacks with contributions by D. Amberti, John Wiley and Sons, 2013. This second revised and expanded second edition.

Details

Package:	mistat
Type:	Package
Date:	2012-08-22
License:	GPL >= 2

Author(s)

Daniele Amberti

Maintainer: Daniele Amberti <amberti@inwind.it>

See Also

Bootstrap Resampling, Quality Control Charts, Operating Characteristics of an Acceptance
Sampling Plan, Quality Control Charts, Fractional Factorial 2-level designs.

Examples

```
data(OELECT)
data(OELECT1)

randomizationTest(list(a=OELECT, b=OELECT1),
                  R=500, calc=mean,
                  fun=function(x) x[1]-x[2],
                  seed=123)

Ps <- pistonSimulation(
  m = rep(60, 100),
  s = rep(0.02, 100),
  v0 = rep(0.01, 100),
  k = rep(5000, 100),
  p0 = rep(110000, 100),
  t = c(rep(296,35), 296*1.1^(1:65)),
  t0 = rep(360, 100),
  each = 1,
  seed = 123,
  check = FALSE)

head(Ps)

cusumArl(mean= 0.0,
         N=100,
         limit=5000,
         seed=123)

powerCircuitSimulation(seed=123, each=3)

set.seed(123)

Ttf <- rgamma(50,
              shape=2,
              scale=100)

Ttr <- rgamma(50,
              shape=2,
              scale=1)

AvailEbd <- availDis(ttf=Ttf,
                     ttr=Ttr,
                     n=1000, seed=123)


RenewEbd <- renewDis(ttf=Ttf,
                     ttr=Ttr,
```

```
                time=1000,
                n=1000)
```

ABC	*ABC*

Description

A customer satisfaction survey, ABC.csv. The data consists of 266 responses to a questionnaire with a question on overall satisfaction (q1) and responses to 125 other questions. Variables named as "q" and a number are satisfaction or agreement levels on a 0-5 scale, Variables named as "qi" represent importance on a 1-3 scale.

Usage

```
data("ABC")
```

Format

A data frame with 266 observations on the following 134 variables.

q1 a numeric vector

q4 a numeric vector

q5 a numeric vector

q6 a numeric vector

qi6 a numeric vector

q7 a numeric vector

qi7 a numeric vector

q8 a numeric vector

qi8 a numeric vector

q9 a numeric vector

qi9 a numeric vector

q10 a numeric vector

qi10 a numeric vector

q11 a numeric vector

q12 a numeric vector

qi12 a numeric vector

q13 a numeric vector

qi13 a numeric vector

q14 a numeric vector

qi14 a numeric vector

q15 a numeric vector

qi15 a numeric vector

q16 a numeric vector

qi16 a numeric vector

q17 a numeric vector

q18 a numeric vector

qi18 a numeric vector

q19 a numeric vector

qi19 a numeric vector

q20 a numeric vector

qi20 a numeric vector

q21 a numeric vector

qi21 a numeric vector

q22 a numeric vector

qi22 a numeric vector

q23 a numeric vector

qi23 a numeric vector

q24 a numeric vector

qi24 a numeric vector

q25 a numeric vector

q26 a numeric vector

qi26 a numeric vector

q27 a numeric vector

qi27 a numeric vector

q28 a numeric vector

qi28 a numeric vector

q29 a numeric vector

qi29 a numeric vector

q30 a numeric vector

qi30 a numeric vector

q31 a numeric vector

q32 a numeric vector

qi32 a numeric vector

q33 a numeric vector

qi33 a numeric vector

q34 a numeric vector

qi34 a numeric vector

q35 a numeric vector

qi35 a numeric vector

q36 a numeric vector

qi36 a numeric vector

q37 a numeric vector

qi37 a numeric vector

q38 a numeric vector

q39 a numeric vector

q40 a numeric vector

q41 a numeric vector

qi41 a numeric vector

q42 a numeric vector

q43 a numeric vector

q44 a numeric vector

q45 a numeric vector

qi45 a numeric vector

q46 a numeric vector

qi46 a numeric vector

q47 a numeric vector

qi47 a numeric vector

q48 a numeric vector

qi48 a numeric vector

q49 a numeric vector

q50 a numeric vector

qi50 a numeric vector

q51 a numeric vector

qi51 a numeric vector

q52 a numeric vector

qi52 a numeric vector

q53 a numeric vector

qi53 a numeric vector

q54 a numeric vector

qi54 a numeric vector

q55 a numeric vector

qi55 a numeric vector

q56 a numeric vector

qi56 a numeric vector

q57 a numeric vector

q58 a numeric vector

qi58 a numeric vector

q59 a numeric vector

qi59 a numeric vector

q60 a numeric vector

qi60 a numeric vector

q61 a numeric vector

qi61 a numeric vector

q62 a numeric vector

qi62 a numeric vector

q63 a numeric vector

qi63 a numeric vector

q64 a numeric vector

qi64 a numeric vector

q65 a numeric vector

q66 a numeric vector

qi66 a numeric vector

q67 a numeric vector

q68 a numeric vector

q70 a numeric vector

q71 a numeric vector

q72 a numeric vector

q73 a numeric vector

q74 a numeric vector

q75 a numeric vector

q76 a numeric vector

q77 a numeric vector

q78 a numeric vector

q79 a numeric vector

q80 a numeric vector

q81 a numeric vector

var1 Continent, a factor with levels Europe

var3 Country, a factor with levels Benelux France Germany Italy UK Israel

var4 Segmentation, a factor with levels Other Silver Gold Platinum

var6 Age of ABC's equipment, a factor with levels less than 1 1-2 2-3 3-4 more than 4

var9 Profitability, a factor with levels Profitable Break-Even Below Break-Even

var11 Position, a factor with levels Owner Management Technical management Technical staff
    Operator Administrator Other

customerSeniority a numeric vector

country a factor with levels Benelux France Germany Israel Italy UK

Source

Kenett, R and Salini, S. (2013) *Modern Analysis of Customer Surveys*.

References

The ABC Company, Questionnaire and Data

Examples

```
data(ABC)
barplot(table(ABC$q1, ABC$q4))
```

ALMPIN   *Aluminium Pins (6 dimensions)*

Description

Records of 6 dimension variables (a subset of 2 in ALMPIN2) measured in mm on 70 alluminium pins used in airplanes, in order of production.

Usage

```
data(ALMPIN)
```

Format

A data frame with 70 observations on the following 6 variables.

diam1 pin diameter at specified location, a numeric vector

diam2 pin diameter at specified location, a numeric vector

diam3 pin diameter at specified location, a numeric vector

capDiam diameter of the cap on top of the pin, a numeric vector

lenNocp length of the pin without the cap, a numeric vector

lenWcp length of the pin with the cap, a numeric vector

Details

The aluminum pins are inserted with air-guns in pre-drilled holes in order to combine critical airplane parts such as wings, engine supports and doors.

The measurements were taken in a computerized numerically controlled (CNC) metal cutting operation. The six variables are Diameter 1, Diameter 2, Diameter 3, Cap Diameter, Lengthncp and Lengthwcp. All the measurements are in millimeters. The first three variables give the pin diameter at three specified locations. Cap Diameter is the diameter of the cap on top of the pin. The last two variables are the length of the pin, without and with the cap, respectively.

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(ALMPIN)

cor(ALMPIN)

plot(ALMPIN)
```

ARMA   *Random realization of ARMA prcess*

Description

Creates a random realization an of ARMA prcess.

Usage

```
ARMA(n, a, b)
```

Arguments

n	length of the ARMA process to be generated.
a	vector p of parameters.
b	vector q of parameters.

Value

a vector with values from the simulated AMRA process of lenght n + max(p, q)

Author(s)

Shelemyahu Zacks

See Also

[predARMA](#)

Examples

```
ARMA(100,c(0.1, 0.2, 0.3), c(0.1, 0.2))
```

---

availDis   *Availability Distribution*

Description

Provide the Empirical Bootstrap Distribution of the asymptotic availability index A_∞, based on observed samples of failure times and repair times.

Usage

```
availDis(ttf, ttr, n, seed = NA, printSummary = TRUE)
```

Arguments

ttf	numeric vector of Time To Failure
ttr	numeric vector of Time To Repair
n	the number of bootstrap replicates
seed	a single value, interpreted as an integer. If specified make the simulation replicable.
printSummary	logical, if TRUE print the Mean Time To Failure, Mean Time To Repair and the asymptotic availability

Value

A numeric vector of lenght n with simulated availabilities

Author(s)

Daniele Amberti

References

Kenett, R., Zacks, S. with contributions by Amberti, D. *Modern Industrial Statistics: with applications in R, MINITAB and JMP*. Wiley.

See Also

renewDis

Examples

```
set.seed(123)

Ttf <- rgamma(50,
              shape=2,
              scale=100)
```

```
Ttr <- rgamma(50,
              shape=2,
              scale=1)

AvailEbd <- availDis(ttf=Ttf,
                     ttr=Ttr,
                     n=1000)
```

BLEMISHES   *Number of Blemishes on Ceramic Plates*

Description

Blemishes found on each of 30 ceramic plates.

Usage

```
data(BLEMISHES)
```

Format

A data frame with 30 observations:

plateID a factor

count an integer vector

Details

Blemishes will affect the final product's (hybrid micro electronic components) electrical performance and its overall yield

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(BLEMISHES)
table(factor(BLEMISHES$count, levels=0:5))
```

CAR   *Car*

Description

Records on 109 different car models, including number of cylinders, origin, turn diamater, horse-power, and number of miles per gallon in city driving.

Usage

```
data(CAR)
```

Format

A data frame with 109 observations on the following 5 variables.

cyl Number of cylinders, an integer vector

origin Car origin, 1 = US; 2 = Europe; 3 = Asia, an integer vector

turn Turn diamater, a numeric vector

hp Horsepower, a numeric vector

mpg Miles per gallon in city driving, a numeric vector

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(CAR)

with(data=CAR, expr=table(cyl, origin))
```

COAL   *Number of Coal Mine Disasters*

Description

Data on the number of coal mine disasters (explosions) in England, per year, for the period 1850 to 1961.

Usage

```
data(COAL)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(COAL)
Bp <- barplot(COAL)

axis(side=1,
     labels=seq(
       from=1850,
       to=1960,
       by=10),
     at=Bp[rep(c(TRUE,
                 rep(FALSE, 9)),
               10)])

rm(Bp)
```

COMPURESP   *Computer Response Time Optimization*

Description

The experiment described here was part of an extensive effort to optimize a UNIX operating system.

Usage

```
data(COMPURESP)
```

Format

A data frame with 18 observations on the following 10 variables.

F a factor with levels 1 2, representing KMCs used

B a factor with levels 1 2 3, representing File Distribution

C a factor with levels 1 2 3, representing Memory Size

D a factor with levels 1 2 3, representing System Buffers

E a factor with levels 1 2 3, representing Sticky Bits

A a factor with levels 1 2 3, representing Disk Drives

G a factor with levels 1 2 3, representing INODE Table Entries

H a factor with levels 1 2 3, representing Other System Tables

Mean mean time taken for the system to complete commands execution

SN S/N ratio $\eta = -10log_{10}(\frac{1}{n}\sum_i y_i^2)$

Details

The experiment described here was part of an extensive effort to optimize a UNIX operating system running on a VAX 11-780 machine. The machine had 48 user terminal ports, two remote job entry links, four megabytes of memory, and five disk drives. The typical number of users logged on at a given time was between 20 to 30.

1. Problem Definition. Users complained that the system performance was very poor, especially in the afternoon. The objective of the improvement effort was to both minimize response time and reduce variability in response.

2. Response variable. In order to get an objective measurement of the response time two specific representative commands called 'standard' and 'trivial' were used. The 'standard' command consisted of creating, editing and removing a file. The 'trivial' command was the UNIX system 'date' command. Response times were measured by submitting these commands every 10 minutes and clocking the time taken for the system to complete their execution.

Source

Pao, Phadke and Sherrerd (1985)

Examples

```
data(COMPURESP)

layout(matrix(1:4, 2, byrow=TRUE))

with(COMPURESP,
     interaction.plot(
       x.factor=F,
       trace.factor=rep(0, length(F)),
       response=SN,
       legend=FALSE,
       type="b",
       pch=15:18,
       ylim=c(-17, -10)))

with(COMPURESP,
     interaction.plot(
       x.factor=B,
       trace.factor=rep(0, length(B)),
       response=SN,
       legend=FALSE,
       type="b",
       pch=15:18,
       ylim=c(-17, -10)))

with(COMPURESP,
     interaction.plot(
       x.factor=C,
       trace.factor=rep(0, length(C)),
       response=SN,
       legend=FALSE,
```

```
        type="b",
        pch=15:18,
        ylim=c(-17, -10)))

with(COMPURESP,
     interaction.plot(
        x.factor=D,
        trace.factor=rep(0, length(D)),
        response=SN,
        legend=FALSE,
        type="b",
        pch=15:18,
        ylim=c(-17, -10)))

layout(1)
```

CONTACTLEN	*Length of the Electrical Contacts*

Description

length (in cm) of the electrical contacts of relays in samples of size five, taken hourly from a running process.

Usage

```
data(CONTACTLEN)
```

Format

A numeric matrix with five columns representing a sample and twenty rows representing hourly samples.

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(CONTACTLEN)

library(qcc)

qcc(CONTACTLEN, type="xbar")
```

---

cusumArl   *Cumulative Sum Control Charts Average Run Length*

Description

Computes the ARL function by simulation

Usage

```
cusumArl(..., randFunc = rnorm, N = 100, limit = 10000, seed = NA,
        kp = 1, km = -1, hp = 3, hm = -3, side = "both",
        printSummary = TRUE)
```

Arguments

`...`	arguments such as mean, lambda or sd to be passed to the appropriate random genneration function
`randFunc`	a random generation function
`N`	the number of replicates
`limit`	safety parameter, stop rule for procedures with very long ARL
`seed`	a single value, interpreted as an integer. If specified make the simulation replicable.
`kp`	K^+ parameter of the control scheme
`km`	K^- parameter of the control scheme
`hp`	h^+ parameter of the control scheme
`hm`	h^- parameter of the control scheme
`side`	a character string specifying the side of the control scheme, must be one of "both" (default), "upper" or "lower"
`printSummary`	logical, if TRUE print a summary of the cusum ARL

Value

a list with elements:

`rls`	a numeric vector representing the Run Length of the simulation
`statistics`	a numeric vector with summary statistics
`run`	a list of length `N` elements each of which has single numeric elements `violationLower`, `violationUpper` and `rl`

Author(s)

Daniele Amberti

References

Kenett, R., Zacks, S. with contributions by Amberti, D. *Modern Industrial Statistics: with applications in R, MINITAB and JMP*. Wiley.

Examples

```
cusumArl(mean=1, seed=123, N=100, limit=1000)

cusumArl(size=100, prob=0.05, kp=5.95, km=3.92, hp=12.87, hm=-8.66,
  randFunc=rbinom, seed=123, N=100, limit=2000)

cusumArl(lambda=10, kp=12.33, km=8.41, hp=11.36, hm=-12.91,
  randFunc=rpois, seed=123, N=100, limit=2000)
```

---

cusumPfaCed   *Cusum Probability of False Alarm and Conditional Expected Delay*

Description

Compute the Probability of False Alarm, PFA, and the Conditional Expected Delay, CED, for the Normal, Binomial and Poisson distributions

Usage

```
cusumPfaCedBinom(size0 = 0, prob0 = 1, size1 = 0, prob1 = 1,
                 tau = 10, N = 100, limit = 10000, seed = NA,
                 kp = 1, km = -1, hp = 3, hm = -3, side = "both",
                 printSummary = TRUE)

cusumPfaCedNorm(mean0 = 0, sd0=1, mean1=0, sd1=1,
                tau=10, N=100, limit=10000, seed=NA,
                kp=1, km=-1, hp=3, hm=-3, side="both",
                printSummary = TRUE)

cusumPfaCedPois(lambda0 = 0, lambda1=1,
                tau=10, N=100, limit=10000, seed=NA,
                kp=1, km=-1, hp=3, hm=-3, side="both",
                printSummary = TRUE)
```

Arguments

size0	number of trials (zero or more)
prob0	probability of success on each trial
size1	number of trials (zero or more) after a process level change
prob1	probability of success on each trial after a process level change
mean0	distribution mean

sd0	distribution standard deviation
mean1	distribution mean after a process level change
sd1	distribution standard deviation after a process level change
lambda0	(non-negative) mean
lambda1	(non-negative) mean after a process level change
tau	time on which the process level change occurs
N	the number of replicates
limit	safety parameter, stop rule for procedures with very long ARL
seed	a single value, interpreted as an integer. If specified make the simulation replicable.
kp	K^+ parameter of the control scheme
km	K^- parameter of the control scheme
hp	h^+ parameter of the control scheme
hm	h^- parameter of the control scheme
side	a character string specifying the side of the control scheme, must be one of "both" (default), "upper" or "lower"
printSummary	logical, if TRUE print a summary of the cusum PFA and CED

Value

a list with elements:

rls	a numeric vector representing the Run Length of the simulation
statistics	a numeric vector with summary statistics
run	a list of length N elements each of which has single numeric elements violationLower, violationUpper and rl

Author(s)

Daniele Amberti

References

Kenett, R., Zacks, S. with contributions by Amberti, D. *Modern Industrial Statistics: with applications in R, MINITAB and JMP*. Wiley.

Examples

```
cusumPfaCedNorm(mean1=1.5,
                tau=100,
                N=100,
                limit=1000,
                seed=123)
```

CYCLT   *50 Cycle Times*

Description

50 cycle times (in seconds) of a piston operating at fixed operating conditions set at the minimal levels of seven control factors.

Usage

```
data(CYCLT)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(CYCLT)

summary(CYCLT)

plot(CYCLT, type="b")
```

DISS   *Dissolution Data*

Description

Dissolution data of a new product and a reference approved product.

Usage

```
data(DISS)
```

Format

A data frame with 12 observations on the following 4 variables.

batch a factor with levels REF TEST

tablet a factor with levels 1 2 3 4 5 6

min15 a numeric vector

min90 a numeric vector

Source

Tsong et al., (1996).

Examples

```
data(DISS)
## maybe str(DISS) ; plot(DISS) ...
```

```
DISSOLUTION                    DISSOLUTION
```

Description

12 test and reference tablets measured under dissolution conditions at 5, 10, 15, 20, 30 and 45 seconds. The level of dissolution recorded for the tested generic product is ideally identical to the brand reference.

Usage

```
data("DISSOLUTION")
```

Format

A data frame with 144 observations on the following 4 variables.

Product a factor with levels R T

Time a numeric vector

Label a factor with levels T1 T10 T10R T11 T11R T12 T12R T1R T2 T2R T3 T3R T4 T4R T5 T5R T6 T6R T7 T7R T8 T8R T9 T9R

Data a numeric vector

Examples

```
data(DISSOLUTION)
Test <- subset(DISSOLUTION, Product == "T")
Test <- reshape(data = Test, v.names = "Data", timevar = "Label",idvar = "Time", direction = "wide")
summary(Test)
# library(fdapace)
# Model <- FPCA(Ly = Test[, grep("Data", colnames(Test))],
#  Lt = Test[, rep("Time", length(grep("Data", colnames(Test))))],
#  optns = list(maxK = 5, methodSelectK = 5))
# plot(Model)
```

---

dlmLg   *Dynamic Linear Model with linear growth*

Description

Dynamic Linear Model with linear growth.

Usage

```
dlmLg(x, C0, v, W, M0)
```

Arguments

x	a vector of data X_t.
C0	prior covariance matrix
v	prior variance of V.
W	prior variance of W.
M0	prior mean.

Value

a vector with values from the Dynamic Linear Model.

Author(s)

Shelemyahu Zacks

Examples

```
C0 <- matrix(c(0.22325, -0.00668, -0.00668, 0.00032), nrow = 2, byrow = TRUE)
W <- matrix(c(0.3191, -0.0095, -0.0095, 0.0004), nrow = 2, byrow = TRUE)
M0 <- matrix(c(134.234, -0.3115), nrow = 2)
v <- 0.1

data(DOW1941)
plot(DOW1941$Date, DOW1941$DOW1941,
     type="l",
     ylab="Dow Jones 1941", xlab="Date")

lines(DOW1941$Date, dlmLg(DOW1941$DOW1941, C0 = C0, v = v, W = W, M0 = M0))
```

DOJO1935 *Dow-Jones Financial Index 1935*

Description

The Dow-Jones financial index for the 300 business days of 1935.

Usage

```
data(DOJO1935)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(DOJO1935)

plot(DOJO1935,
     type="b",
     ylab="Dow Jones")
```

DOW1941 *Dow-Jones Financial Index 1941*

Description

The Dow-Jones daily index of 1941.

Usage

```
data("DOW1941")
```

Format

A data frame with 302 observations on the following 5 variables.

DOW1941 Dow-Jones daily value

Date a POSIXlt

Day a progressive number

DayOfWeek a factor representing the weekday with levels 1 2 3 4 5 6

Month a factor representing the month with levels 1 2 3 4 5 6 7 8 9 10 11 12

Examples

```
data(DOW1941)

plot(DOW1941$Date, DOW1941$DOW1941,
     type="l",
     ylab="Dow Jones 1941", xlab="Date")
```

---

dynOAB   *Dynamic programming of the optimal One-Armed Bandits*

Description

Dynamic programming of the optimal One-Armed Bernoulli Bandits process

Usage

```
dynOAB(N, al)
```

Arguments

N	number of trials.
al	the known probability of reward on arm A.

Value

For dynOAB the matrix of maximal predicted rewards. For dynOAB2 the optimal predicted reward.

Author(s)

Shelemyahu Zacks

See Also

[simOAB](#)

Examples

```
dynOAB(10, 0.5)
dynOAB2(10, 0.5)
```

ELECFAIL   *Failures of an Electronic Device*

Description

50 failure times of an electronic device.

Usage

```
data(ELECFAIL)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(ELECFAIL)

hist(ELECFAIL)
```

ELECINDX   *Bernoulli Sample on OELECT Data*

Description

Bernoulli sample in which, we give a circuit in OELECT the value 1 if its electric output is in the interval (216, 224) and the value 0 otherwise.

Usage

```
data(ELECINDX)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

See Also

[OELECT](#)

Examples

```
data(ELECINDX)

qbinom(p=0.5, size=100, prob=mean(ELECINDX))
```

ETCHRATE	*Data on the Rate of Etching*

Description

Rate of removal of field oxide in a semiconductor plasma etching process.

Usage

```
data(ETCHRATE)
```

Source

Digital Equipment Corporation (1988).

Examples

```
data(ETCHRATE)

hist(ETCHRATE)
```

ETCHRATETWO	*Data on the Rate of Etching (two samples)*

Description

Rate of removal of field oxide in two different semiconductor plasma etching processes, A and B.

Usage

```
data(ETCHRATETWO)
```

Format

A data frame with 12 observations on the following 2 variables.

A a numeric vector, rate of etching, sample A
B a numeric vector, rate of etching, sample B

Source

Digital Equipment Corporation (1988).

Examples

```
data(ETCHRATETWO)

boxplot(values ~ ind, data=stack(ETCHRATETWO))
```

FAILTIME   *Failure Times*

Description

Failure times of 20 electric generators (in hr).

Usage

```
data(FAILTIME)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(FAILTIME)

library(survival)

SuRe <- survreg(
  Surv(time=FAILTIME) ~ 1 ,
  dist = "exponential")

summary(SuRe)
```

FILMSP   *Film Speed*

Description

Data gathered from 217 rolls of film. The data consists of the film speed as measured in a special lab.

Usage

```
data(FILMSP)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(FILMSP)

hist(FILMSP)
```

FLEXPROD   *The Quinlan Experiment at Flex Products*

Description

Flex Products is a subcontractor of General Motors, manufacturing mechanical speedometer cables. The basic cable design has not changed for fifteen years and General Motors had experienced many disappointing attempts at reducing the speedometer noise level.

Usage

```
data(FLEXPROD)
```

Format

A data frame with 16 observations on the following 16 variables.

A Liner O.D., a factor with levels 1 2

B Liner Die, a factor with levels 1 2

C Liner Material, a factor with levels 1 2

D Liner Line Speed, a factor with levels 1 2

E Wire Braid Type, a factor with levels 1 2

F Braiding Tension, a factor with levels 1 2

G Wire Diameter, a factor with levels 1 2

H Liner Tension, a factor with levels 1 2

I Liner Temperature, a factor with levels 1 2

J Coating Material, a factor with levels 1 2

K Coating Dye Type, a factor with levels 1 2

L Melt Temperature, a factor with levels 1 2

M Screen Pack, a factor with levels 1 2

N Cooling Method, a factor with levels 1 2

O Line Speed, a factor with levels 1 2

SN Signal to noise ratio, a numeric vector

Details

Problem Definition: the product under investigation is an extruded thermoplastic speedometer casing used to cover the mechanical speedometer cable on automobiles. Excessive shrinkage of the casing is causing noise in the mechanical speedometer cable assembly.

Response variable: the performance characteristic in this problem is the post extrusion shrinkage of the casing. The percent shrinkage is obtained by measuring approximately 600mm of casing that has been properly conditioned (A), placing that casing in a two hour heat soak in an air circulating oven, reconditioning the sample and measuring the length (B). Shrinkage is computed as: $Shrinkage = 100 * (A - B)/A$.

Factor Levels: Existing (1) - Changed (2)

Number of Replications: four random samples of 600mm from the 3000 feet manufactured at each experimental run.

Data Analysis: signal to noise ratios (SN) are computed for each experimental run and analyzed using main effect plots and an ANOVA. Savings are derived from Loss function computations.

The signal to noise formula used by Quinlan is:

$$\eta = -10log_{10}(\frac{1}{n} \sum y^2)$$

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(FLEXPROD)

aov(SN ~ . , data=FLEXPROD)
```

FOOD	*FOOD*

Description

Nutritional data from 961 different food items

Usage

```
data("FOOD")
```

Format

A data frame with 961 observations on the following 7 variables.

Fat.grams a numeric vector, fat in grams

FoodEnergy.calories a numeric vector, food energy in calories

Carbohydrates.grams a numeric vector, carbohydrates in grams

Protein.grams a numeric vector, protein in grams

Cholesterol.mg a numeric vector, cholesterol in milligrams

Weight.grams a numeric vector, weight in grams

SaturatedFat.grams a numeric vector, saturated fat in grams

Examples

```
data(FOOD)
plot(FOOD)
```

GASOL   *Distillation Properties of Crude Oils*

Description

32 measurements of distillation properties of crude oils.

Usage

```
data(GASOL)
```

Format

A data frame with 32 observations on the following 5 variables.

x1 crude oil gravity (API), a numeric vector

x2 crude oil vapour pressure (psi), a numeric vector

astm crude oil ASTM 10% point ($Fahrenheit$), a numeric vector

endPt gasoline ASTM endpoint ($Fahrenheit$), a numeric vector

yield yield of gasoline (in percentage of crude oil), a numeric vector

Source

Daniel and Wood (1971) pp. 165

Examples

```
data(GASOL)

LmYield <- lm(yield ~ 1 + astm + endPt,
              data=GASOL)

summary(LmYield)
```

GASTURBINE   *Gas Turbine Cycle Times*

Description

125 gas turbine cycle times divided in 25 samples of 5 observations.

Usage

```
data(GASTURBINE)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(GASTURBINE)

plot(rowMeans(GASTURBINE), type="b")
```

HADPAS   *Resistance Values of Hybrids*

Description

Several resistance measurements (Ω) of five types of resistances (Res 3, Res 18, Res 14, Res 7 and Res 20), which are located in six hybrid micro circuits simultaneously manufactured on ceramic substrates. There are altogether 192 records for 32 ceramic plates.

Usage

```
data(HADPAS)
```

Format

A data frame with 192 observations on the following 7 variables.

diska ceramic plate, a numeric vector

hyb hybrid micro circuit, a numeric vector

res3 a numeric vector

res18 a numeric vector

res14 a numeric vector

res7 a numeric vector

res20 a numeric vector

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(HADPAS)

boxplot(HADPAS$res3 ~ HADPAS$hyb)
```

HYBRID   *Resistance Values of Res 3*

Description

A subset of data in HADPAS, only variable res3 is recorded. HYBRID contains values for hybrids 1 to 3, HYBRID1 contains hybrid 1 data and HYBRID2 contains values of hybrids 1 and 2.

Usage

```
data(HYBRID)
```

Format

A data frame (a vector for HYBRID1) with 32 observations on the following variables.

hyb1 resistance measurements (Ω) of Res 3, a numeric vector

hyb2 resistance measurements (Ω) of Res 3, a numeric vector

hyb3 resistance measurements (Ω) of Res 3, a numeric vector

Source

See HADPAS

Examples

```
data(HYBRID)

lapply(HYBRID, var)
```

INSERTION   *Components Insertions into a Board*

Description

Data represents a large number of insertions with $k = 9$ different components. The result of each trial (insertion) is either Success (no insertion error) or Failure (insertion error).

Usage

```
data(INSERTION)
```

Format

A data frame with 9 (k) observations on the following 3 variables.

comp Component, a factor with levels `C1 C2 C3 C4 C5 C6 C7 C8 C9`

fail Failure, a numeric vector

succ Success, a numeric vector

Details

Components are:

C1: Diode

C2: 1/2 Watt Canister

C3: Jump Wire

C4: Small Corning

C5: Large Corning

C6: Small Bullet

C7: 1/8 Watt Dogbone

C8: 1/4 Watt Dogbone

C9: 1/2 Watt Dogbone

Source

See PLACE

Examples

```
data(INSERTION)

barplot(INSERTION$fail /
          (INSERTION$fail + INSERTION$succ) *
          100,
       names.arg=INSERTION$comp,
       ylab= "Percentage")
```

IPL   *Number of Computer Crashes per Month*

Description

Number of computer crashes per month, due to power failures experienced at a computer center, over a period of 28 months. After a crash, the computers are made operational with an "Initial Program Load".

Usage

```
data(IPL)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(IPL)

plot(IPL, type="b")
```

JANDEFECT   *January Number of Defects in Daily Samples*

Description

Number of defective items found in random samples of size $n = 100$, drawn daily from a production line in January.

Usage

```
data(JANDEFECT)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(JANDEFECT)

plot(JANDEFECT, type="b")
```

KEYBOARDS   *New Designs of Feyboards for Desktop Computers*

Description

The design of the keyboard might have effect on the speed of typing or on the number of typing errors. Noisy factors are typist or type of job. Letters A, B, C, D of variable keyboard denote the designs.

Usage

```
data(KEYBOARDS)
```

Format

A data frame with 25 observations on the following 4 variables.

typist The typist, a factor with levels 1 2 3 4 5

job The type of job, a factor with levels 1 2 3 4 5

keyboard Keyboard design, a factor with levels A B C D E

errors Number of typing errors, a numeric vector

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(KEYBOARDS)

boxplot(errors ~ keyboard, data=KEYBOARDS, ylab="Errors")
```

LATHYPPISTON   *Latin Hypercube Design for the Piston Simulator*

Description

A Latin Hypercube Design for the 7 `pistonSimulation` arguments and Its response in seconds.

Usage

```
data(LATHYPPISTON)
```

Format

A data frame with 14 observations on the following 8 variables.

m a numeric vector

s a numeric vector

v0 a numeric vector

k a numeric vector

p0 a numeric vector

t a numeric vector

t0 a numeric vector

seconds a numeric vector

Source

Kenett, R., Zacks, S. with contributions by Amberti, D. *Modern Industrial Statistics: with applications in R, MINITAB and JMP*. Wiley.

See Also

[pistonSimulation](#)

Examples

```
data(LATHYPPISTON)

library(DiceEval)

Dice <- km(design=LATHYPPISTON[, !names(LATHYPPISTON) %in% "seconds"],
           response=LATHYPPISTON[,"seconds"])

library(DiceView)

sectionview(Dice,
            center=colMeans(LATHYPPISTON[, !names(LATHYPPISTON) %in% "seconds"]),
            conf_lev=c(0.5, 0.9, 0.95),
```

```
              title="", col_sur="darkgrey", lwd=2,
              Xname=colnames(LATHYPPISTON[, !names(LATHYPPISTON) %in% "seconds"]))


    layout(1)
```

---

mahalanobisT2	*Mahalanobis T^2*

Description

Mahalanobis T^2 and Confidence Region

Usage

```
mahalanobisT2(x, factor.name, response.names = names(x)[!names(x) %in% factor.name],
conf.level=0.95, compare.to = NA, plot = FALSE)
```

Arguments

x	a data frame
factor.name	single character indicating column name of the experiment factor to test, the first level is used as a reference
response.names	vector of characters indicating columns names of the responses
conf.level	confidence level for the Confidence Region
compare.to	a vector of length `length(response.names)` to be compared to the result in terms of Mahalanobis T^2
plot	logical, if TRUE also a plot is produced

Value

a list with components:

coord	matrix with transformed coordinates of variables in `response.names`
mahalanobis	vector containing Lower Control Region, Center and Upper Control Region of Mahalanobis T^2
mahalanobis.compare	
	single value, Mahalanobis T^2 of `compare.to`

Author(s)

Daniele Amberti

References

Kenett, R., Zacks, S. with contributions by Amberti, D. *Modern Industrial Statistics: with applications in R, MINITAB and JMP*. Wiley.

Tsong et al, (1996).

Examples

```
data(DISS)

mahalanobisT2(DISS[, c("batch", "min15", "min90")],
              factor.name="batch",
              conf.level=0.90,
              compare.to=c(15, 15))
```

---

masPred1   *Moving Average Smoothing Predictor*

Description

A moving average smoother is a sequence which replaces X_t by a fitted polynomial based on the window of size n = 2m + s around X_t. The simplest smoother is the linear one.

Usage

```
masPred1(x, m, s)
```

Arguments

x	a vector of data X_t.
m	the m to define the window size.
s	the s to define the window size.

Value

a vector with values form the linear smoother predictor.

Author(s)

Shelemyahu Zacks

Examples

```
set.seed(123)
x <- 1:20 + rnorm(20, 0, 0.1)
masPred1(x, m = 3, s= 1)
masPred1(x, m = 3, s= 3)

data(DOW1941)
plot(DOW1941$Date, DOW1941$DOW1941,
     type="l",
     ylab="Dow Jones 1941", xlab="Date")
lines(DOW1941$Date, masPred1(DOW1941$DOW1941, m = 3, s= 1))
```

MPG   *Gasoline Consumption of Cars by Origin*

Description

Gasoline consumption (in miles per gallon in city driving) of cars by origin. There are 3 variables representing samples of sizes $n1 = 58$, $n2 = 14$ and $n3 = 37$.

Usage

```
data(MPG)
```

Format

A data frame with 58 observations on the following 3 variables.

origin1 Gasoline consumption, a numeric vector

origin2 Gasoline consumption, a numeric vector

origin3 Gasoline consumption, a numeric vector

Source

See CAR

Examples

```
data(MPG)

library(boot)

set.seed(123)

B <- apply(MPG, MARGIN=2,
           FUN=boot,
           statistic=function(x, i){
             var(x[i], na.rm = TRUE)
           },
           R = 500)

Bt0 <- sapply(B,
              FUN=function(x) x$t0)

Bt <-  sapply(B,
              FUN=function(x) x$t)

Bf <- max(Bt0)/min(Bt0)

FBoot <- apply(Bt, MARGIN=1,
               FUN=function(x){
```

```
                  max(x)/min(x)
               })

   Bf

   quantile(FBoot, 0.95)

   sum(FBoot >= Bf)/length(FBoot)

   rm(Bt0, Bt, Bf, FBoot)
```

---

nrwm   *Normal Random Walk*

Description

Normal Random Walk with a Bayesian prediction.

Usage

```
nrwm(n, v, w, c)
```

Arguments

n	length.
v	prior variance of V_0.
w	prior variance of W_0.
c	variance of the prior Normal Distribution.

Value

nrw	realizations of a Normal Random Walk
Mt	posterior expectation m_t

Author(s)

Shelemyahu Zacks

Examples

```
nrwm(n = 10, v = 5, w = 8, c = 0.5)
```

OELECT   *Electric Voltage Outputs of Rectifying Circuits*

Description

99 electric voltage outputs of a rectifying circuit (V).

Usage

```
data(OELECT)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(OELECT)

summary(OELECT)

mean(OELECT)
```

OELECT1   *Electric Voltage Outputs of Another Rectifying Circuit*

Description

25 electric voltage outputs of a rectifying circuit (V).

Usage

```
data(OELECT1)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(OELECT)

data(OELECT1)

randomizationTest(list(a=OELECT, b=OELECT1),
                  R=500, calc=mean,
                  fun=function(x) x[1]-x[2])
```

OTURB   *Cycle Times of a Piston*

Description

100 cycle times (s) of a piston, as from pistonSimulation.

Usage

```
data(OTURB)
```

References

See pistonSimulation

Examples

```
data(OTURB)

plot(OTURB, type="b")
```

OTURB1   *Cycle Times of a Piston from the Piston Simulator*

Description

50 cycle times (in s)of a piston gerated with pistonSimulation(seed=123). Cycle times are rounded to 3 decimals.

Usage

```
data(OTURB1)
```

References

See pistonSimulation

Examples

```
data(OTURB1)

REF <- round(pistonSimulation(seed=123)$seconds, 3)

plot(OTURB1, type="b", lwd=6)

lines(REF, col=2, lwd=2)

sum(OTURB1 - REF)
```

OTURB2   *Sample Mean and Standard Deviation of Cycle Times of a Piston*

Description

In this data frame we have three variables. In the first we have the sample size. In the second and third we have the sample means and standard deviation.

Usage

```
data(OTURB2)
```

Format

A data frame with 10 observations on the following 3 variables.

groupSize a numeric vector

xbar a numeric vector

std a numeric vector

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(OTURB2)
plot(OTURB2$xbar, type="b")
plot(OTURB2$std, type="b")
```

PBX   *Software Errors Found in Testing a PBX*

Description

Software errors found in testing a Private Branch Exchange electronic switch. Errors are labeled according to the software unit where they occurred (e.g. "EKT", Electronic Key Telephone).

Usage

```
data(PBX)
```

Format

The format is: Named num [1:5] 473 252 110 100 65 - attr(*, "names")= chr [1:5] "GEN" "VHS" "HI" "LO" ...

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(PBX)

barplot(PBX)
```

---

pistonSimulation   *The Piston Simulator*

Description

A simulator of a piston moving whithin a cylinder. The piston's performance is measured by the time it takes to complete one cycle, in seconds. Several factors can affect the piston's performance, they are listed in the arguments section.

Usage

```
pistonSimulation(m = 60, s = 0.02, v0 = 0.01,
                 k = 5000, p0 = 110000, t = 296,
                 t0 = 360, each = 50, seed = NA,
                 check = TRUE)
```

Arguments

m	the impact pressure determined by the piston weight (kg). A single value or a vector of length *n*.
s	the piston surface area (m^2). A single value or a vector.
v0	the initial volume of the gas inside the piston (m^3). A single value or a vector of length *n*.
k	the spring coefficient (N/m^3). A single value or a vector of length *n*.
p0	the atmospheric pressure (N/m^2). A single value or a vector of length *n*.
t	the surrounding ambient temperature (K). A single value or a vector of length *n*.
t0	the filling gas temperature (K). A single value or a vector of length *n*.
each	non-negative integer. Each element of previous parameters is repeated each times.

seed	a single value, interpreted as an integer. If specified make the simulation replicable.
check	if TRUE (the default) then a formal check on piston parameters is perfomed

Details

Factors affect the Cycle Time s via a chain of nonlinear equations:

$$s = 2\pi \sqrt{\frac{M}{k + S^2 \frac{P_0 V_0}{T_0} \frac{T}{V^2}}}$$

where

$$V = \frac{S}{2k} \sqrt{A^2 + 4k \frac{P_0 V_0}{T_0} T} - a$$

and

$$A = P_0 S + 19.62M - \frac{kV_0}{S}$$

Value

A data frame, a matrix-like structure, with each * *n* rows and with columns:

m	numeric	value of m
s	numeric	value of s
v0	numeric	value of v0
k	numeric	value of k
p0	numeric	value of p0
t	numeric	value of t
t0	numeric	value of t0
seconds	numeric	time to complete one cycle (s)

Author(s)

Daniele Amberti

References

Kenett, R., Zacks, S. with contributions by Amberti, D. *Modern Industrial Statistics: with applications in R, MINITAB and JMP*. Wiley.

See Also

powerCircuitSimulation, simulationGroup, LATHYPPISTON

Examples

```
Ps <- pistonSimulation(
  m = rep(60, 100),
  s = rep(0.02, 100),
  v0 = rep(0.01, 100),
```

```
  k = rep(5000, 100),
  p0 = rep(110000, 100),
  t = c(rep(296,35), 296*1.1^(1:65)),
  t0 = rep(360, 100),
  each = 1,
  seed = 123,
  check = FALSE)
head(Ps)
tail(Ps)
plot(Ps$seconds)
```

PLACE	*Displacements of Electronic Components on Printed Circuit Boards*

Description

The observations are the displacements (position errors) of electronic components on printed circuit boards. There are 26 boards. 16 components are placed on each board. Each component has to be placed at a specific location (x, y) on a board and with correct orientation θ.

Usage

```
data(PLACE)
```

Format

A data frame with 416 observations on the following 4 variables.

crcBrd Circuit board number, a numeric vector

xDev Error in placement along the x-axis, a numeric vector

yDev Error in placement along the y-axis, a numeric vector

tDev Error in orientation θ, a numeric vector

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(PLACE)

plot(PLACE[,-1])

boxplot(xDev ~ crcBrd, data=PLACE,
        ylab="xDev", xlab="crcBrd")

PLACE$code <- factor(c(rep("lDev", 9*16),
```

```
                    rep("mDev", 3*16),
                    rep("hDev", 14*16)))

plot(PLACE[,"xDev"], PLACE[,"yDev"],
     pch=as.integer(PLACE[,"code"]),
     main="", xlab="xDev", ylab="yDev")

grid()
```

---

powerCircuitSimulation

The Power Circuit Simulator

Description

A simulator of a voltage conversion power circuit. The target output voltage of the power circuit is 220 volts DC. The circuit consists of 10 resistances labeled *A* to *J*, and 3 transistors, labeled *K* to *M*. These components can be purchased with different tolerance grades.

Usage

```
powerCircuitSimulation(rsA = 8200, rsB = 220000, rsC = 1000,
                       rsD = 33000, rsE = 56000, rsF = 5600,
                       rsG = 3300, rsH = 58.5, rsI = 1000,
                       rsJ = 120, trK = 130, trL = 100,
                       trM = 130,
                       tlA = 5, tlB = 10, tlC = 10,
                       tlD = 5, tlE = 5, tlF = 5,
                       tlG = 10, tlH = 5, tlI = 5,
                       tlJ = 5, tlK = 5, tlL = 10,
                       tlM = 5,
                       each = 50, seed = NA)
```

Arguments

rsA	the resistance (Ω) of *A*. A single value or a vector of length *n*.
rsB	the resistance (Ω) of *B*. A single value or a vector of length *n*.
rsC	the resistance (Ω) of *C*. A single value or a vector of length *n*.
rsD	the resistance (Ω) of *D*. A single value or a vector of length *n*.
rsE	the resistance (Ω) of *E*. A single value or a vector of length *n*.
rsF	the resistance (Ω) of *F*. A single value or a vector of length *n*.
rsG	the resistance (Ω) of *G*. A single value or a vector of length *n*.
rsH	the resistance (Ω) of *H*. A single value or a vector of length *n*.
rsI	the resistance (Ω) of *I*. A single value or a vector of length *n*.

rsJ	the resistance (Ω) of *J*. A single value or a vector of length *n*.
trK	the resistance (Ω) of *K*. A single value or a vector of length *n*.
trL	the resistance (Ω) of *L*. A single value or a vector of length *n*.
trM	the resistance (Ω) of *M*. A single value or a vector of length *n*.
tlA	the tolerance of *A*. It is a number > 0 (e.g. 5% is 5.0)
tlB	the tolerance of *B*. It is a number > 0 (e.g. 5% is 5.0)
tlC	the tolerance of *C*. It is a number > 0 (e.g. 5% is 5.0)
tlD	the tolerance of *D*. It is a number > 0 (e.g. 5% is 5.0)
tlE	the tolerance of *E*. It is a number > 0 (e.g. 5% is 5.0)
tlF	the tolerance of *F*. It is a number > 0 (e.g. 5% is 5.0)
tlG	the tolerance of *G*. It is a number > 0 (e.g. 5% is 5.0)
tlH	the tolerance of *H*. It is a number > 0 (e.g. 5% is 5.0)
tlI	the tolerance of *I*. It is a number > 0 (e.g. 5% is 5.0)
tlJ	the tolerance of *J*. It is a number > 0 (e.g. 5% is 5.0)
tlK	the tolerance of *K*. It is a number > 0 (e.g. 5% is 5.0)
tlL	the tolerance of *L*. It is a number > 0 (e.g. 5% is 5.0)
tlM	the tolerance of *M*. It is a number > 0 (e.g. 5% is 5.0)
each	non-negative integer. Each element of previous parameters is repeated each times.
seed	a single value, interpreted as an integer. If specified make the simulation replicable.

Details

Factors affect the voltage output V via a chain of nonlinear equations:

$$V = \frac{136.67(a + \frac{b}{Z(10)}) + d(c+e)\frac{g}{f} - h}{1 + d\frac{e}{f} + b[frac1Z(10) + 0.006(1 + \frac{13.67}{Z(10)})] + 0.08202a}$$

where

$$a = \frac{Z(2)}{Z(1) + Z(2)}$$

$$b = \frac{1}{Z(12) + Z(13)}(Z(3) + \frac{Z(1)Z(2)}{Z(1) + Z(2)}) + Z(9)$$

$$c = Z(5) + Z(7)/2$$

$$d = Z(11)\frac{Z(1)Z(2)}{Z(1) + Z(2)}$$

$$e = Z(6) + Z(7)/2$$

$$f = (c + e)(1 + Z(11))Z(8) + ce$$

$$g = 0.6 + Z(8)$$

$$h = 1.2$$

with $Z(1), \ldots, Z(10)$ resistances in Ω of the 10 resistances and $Z(11), Z(12), Z(13)$ are the h_{FE} values of three transistors.

Value

A data frame, a matrix-like structure, with each * *n* rows and with columns:

rsA	numeric	value of `rsA`
rsB	numeric	value of `rsB`
rsC	numeric	value of `rsC`
rsD	numeric	value of `rsD`
rsE	numeric	value of `rsE`
rsF	numeric	value of `rsF`
rsG	numeric	value of `rsG`
rsH	numeric	value of `rsH`
rsI	numeric	value of `rsI`
rsJ	numeric	value of `rsJ`
trK	numeric	value of `trK`
trL	numeric	value of `trL`
trM	numeric	value of `trM`
tlA	numeric	value of `tlA`
tlB	numeric	value of `tlB`
tlC	numeric	value of `tlC`
tlD	numeric	value of `tlD`
tlE	numeric	value of `tlE`
tlF	numeric	value of `tlF`
tlG	numeric	value of `tlG`
tlH	numeric	value of `tlH`
tlI	numeric	value of `tlI`
tlJ	numeric	value of `tlJ`
tlK	numeric	value of `tlK`
tlL	numeric	value of `tlL`
tlM	numeric	value of `tlM`
volts	numeric	output in volts (V)

Author(s)

Daniele Amberti

References

Kenett, R., Zacks, S. with contributions by Amberti, D. *Modern Industrial Statistics: with applications in R, MINITAB and JMP*. Wiley.

See Also

[pistonSimulation](), [simulationGroup]()

Examples

```
powerCircuitSimulation(seed=123, each=3)
```

PRED   *Soldering Points*

Description

1,000 records on variable `x` and `y`. `x` is the number of soldering points on a board, and `y` is the number of defective soldering points.

Usage

```
data(PRED)
```

Format

A data frame with 1000 observations on the following 2 variables.

x Number of soldering points, a numeric vector
y Number of defective soldering points, a numeric vector

Details

Electronic systems such as television sets, radios or computers contain printed circuit boards with electronic components positioned in patterns determined by design engineers. After assembly (either by automatic insertion machines or manually) the components are soldered to the board. In the relatively new Surface Mount Technology minute components are simultaneously positioned and soldered to the boards. The occurrence of defective soldering points impacts the assembly plant productivity and is therefore closely monitored

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(PRED)

library(boot)

set.seed(123)

YRatioPred <- boot(data=PRED$x,
                   statistic=function(x,i){
                     mean(x[i[1:100]])*7.495/148.58
                     },
                   R=1000)$t

hist(YRatioPred, main="",
     xlab="",
     xlim=c(7, 8))
```

---

pred1   *Linear Predictor for Covariance Stationary Time Series*

Description

An Optimal Linear Predictor for Covariance Stationary Time Series.

Usage

```
pred1(x, n = 10)
```

Arguments

x   a vector of data X_t.

n   the n to define the window size.

Value

a vector with values form the linear predictor.

Author(s)

Shelemyahu Zacks

Examples

```
pred1(rnorm(20), n = 10)
```

---

predARMA   *Prediction of an AR 3 process*

Description

For isslustration purposes this implements the prediction of an ARMA(3, 0) process.

Usage

```
predARMA(X, a)
```

Arguments

X   a vector of data X_t.

a   vector p of parameters.

Value

a vector with values from the quadratic predictor.

Author(s)

Shelemyahu Zacks

See Also

[ARMA](#)

Examples

```
set.seed(123)
predARMA(ARMA(100,c(0.1, 0.2, 0.3), c(0.1, 0.2)), c(0.1, 0.2, 0.3))
```

---

predPoly   *Quadratic Predictor*

Description

A quadratic polynomial fitted to the last n observations. We then extrapolate to estimate $f(t + s)$ with $s >= 1$.

Usage

```
predPoly(x, n, s)
```

Arguments

x	a vector of data X_t.
n	the n to define the window size.
s	the extrapolation parametr s.

Value

a vector with values from the quadratic predictor.

Author(s)

Shelemyahu Zacks

Examples

```
data(DOW1941)
plot(DOW1941$Date, DOW1941$DOW1941,
     type="l",
     ylab="Dow Jones 1941", xlab="Date")

lines(DOW1941$Date, predPoly(DOW1941$DOW1941, n = 20, s= 1))
```

---

randomizationTest   *Randomization Test*

Description

A function to perform randomization test

Usage

```
randomizationTest(list, R = 500, calc, fun = NA,
                  seed = NA, printSummary = TRUE)
```

Arguments

list	a list with two or more numeric vectors
R	
calc	a function to be applied to every vector in list
fun	a function to be applied to a vector (e.g. x) of length length(list), containing result of function calc
seed	a single value, interpreted as an integer. If specified make the simulation replicable.
printSummary	logical, if TRUE print a summary of the randomization test

Value

The silently returned value is an object of class "boot"

Author(s)

Daniele Amberti

References

Kenett, R., Zacks, S. with contributions by Amberti, D. *Modern Industrial Statistics: with applications in R, MINITAB and JMP*. Wiley.

See Also

[boot](#)

Examples

```
data(OELECT)
data(OELECT1)

# test difference in mean:
randomizationTest(list(a=OELECT, b=OELECT1),
                  R=500, calc=mean,
                  fun=function(x) x[1]-x[2],
                  seed=123)
```

---

renewDis   *Renewals Disribution*

Description

Provide the Empirical Bootstrap Distribution of the number of renewals in a specified time interval.

Usage

```
renewDis(ttf, ttr, time, n, printSummary = TRUE)
```

Arguments

ttf	numeric vector of Time To Failure
ttr	numeric vector of Time To Repair
time	numeric value representing the time horizon on which number of renewals are calculated
n	the number of bootstrap replicates
printSummary	logical, if TRUE print the Mean Number of Renewals, and a summary of renewals values

Value

A numeric vector of lenght n with simulated number of renewals

Author(s)

Daniele Amberti

References

Kenett, R., Zacks, S. with contributions by Amberti, D. *Modern Industrial Statistics: with applications in R, MINITAB and JMP*. Wiley.

See Also

availDis

Examples

```
set.seed(123)

Ttf <- rgamma(50,
              shape=2,
              scale=100)

Ttr <- rgamma(50,
              shape=2,
              scale=1)

RenewEbd <- renewDis(ttf=Ttf,
                     ttr=Ttr,
                     time=1000,
                     n=1000)
```

RNORM10   *Random Sample from N(10, 1)*

Description

Random sample of size $n = 28$ from the normal distribution $N(10, 1)$.

Usage

```
data(RNORM10)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(RNORM10)

plot(RNORM10, type="b")

abline(h=10, lwd=2, col=2)
```

SeasCom   *Monthly demand for a commodity*

Description

Monthly demand for a seasonal commodity during 102 months.

Usage

```
data("SeasCom")
```

Format

The format is: num [1:102] 72 56.4 64.9 59.9 51.6 ...

Examples

```
data(SeasCom)

plot(SeasCom,
     type="b",
     ylab="Dow Jones")
```

SENSORS   *SENSORS*

Description

174 measurements from 63 sensors tracking performance of a system under test. Each test generates values for these 63 sensors and a status determined by the automatic test equipment. The test results are coded as Pass (corresponding to 'Good' and Fail (all other categories).

Usage

```
data("SENSORS")
```

Format

A data frame with 174 observations on the following 65 variables.

sensor01 a numeric vector

sensor02 a numeric vector

sensor03 a numeric vector

sensor04 a numeric vector

sensor05 a numeric vector

`sensor06` a numeric vector
`sensor07` a numeric vector
`sensor08` a numeric vector
`sensor09` a numeric vector
`sensor10` a numeric vector
`sensor11` a numeric vector
`sensor12` a numeric vector
`sensor13` a numeric vector
`sensor14` a numeric vector
`sensor15` a numeric vector
`sensor16` a numeric vector
`sensor17` a numeric vector
`sensor18` a numeric vector
`sensor19` a numeric vector
`sensor20` a numeric vector
`sensor21` a numeric vector
`sensor22` a numeric vector
`sensor23` a numeric vector
`sensor24` a numeric vector
`sensor25` a numeric vector
`sensor26` a numeric vector
`sensor27` a numeric vector
`sensor28` a numeric vector
`sensor29` a numeric vector
`sensor30` a numeric vector
`sensor31` a numeric vector
`sensor32` a numeric vector
`sensor33` a numeric vector
`sensor34` a numeric vector
`sensor35` a numeric vector
`sensor36` a numeric vector
`sensor37` a numeric vector
`sensor38` a numeric vector
`sensor39` a numeric vector
`sensor40` a numeric vector
`sensor41` a numeric vector
`sensor42` a numeric vector

sensor43 a numeric vector

sensor44 a numeric vector

sensor45 a numeric vector

sensor46 a numeric vector

sensor47 a numeric vector

sensor48 a numeric vector

sensor49 a numeric vector

sensor50 a numeric vector

sensor51 a numeric vector

sensor52 a numeric vector

sensor53 a numeric vector

sensor54 a numeric vector

sensor55 a numeric vector

sensor56 a numeric vector

sensor57 a numeric vector

sensor58 a numeric vector

sensor59 a numeric vector

sensor60 a numeric vector

sensor61 a numeric vector

sensor62 a numeric vector

sensor63 a numeric vector

testResult a factor with levels Brake Good Grippers IMP ITM Motor SOS Velocity Type I Velocity Type II

status a factor with levels Fail Pass

Examples

```
data(SENSORS)
library(rpart)
rpart(status ~ . , data=SENSORS[, c("status", "sensor18", "sensor55")])
```

---

shroArlPfaCed	*ARL, PFA and CED of Shiryayev-Roberts procedure*

Description

Average Run Length, the Probability of False Alarm and the Conditional Expected Delay, given that the alarm is given after the change-point for Normal and Poisson cases

Usage

```
shroArlPfaCedNorm(mean0 = 0, mean1 = NA, sd = 1, n = 10,
                  delta = 1, tau = NA, N = 100, limit = 10000,
                  seed = NA, w = 19, printSummary = TRUE)

shroArlPfaCedPois(lambda0 = 10, lambda1 = NA, delta = 1,
                  tau = NA, N = 100, limit = 10000, seed = NA,
                  w = 19, printSummary = TRUE)
```

Arguments

mean0	value of the mean of a normal distributed process
mean1	optional value of the mean after a shift in a normal process, ignored if delta is not NA
sd	standard deviation of a normal distributed process
n	sample size
lambda0	mean of a Poisson distributed process
lambda1	optional value of the mean after a shift in a Poisson process, ignored if delta is not NA
delta	value of the shift from mean0 or lambda0, set to NA if the alternative specification with mean1 or lambda1 is needed
tau	location of the point of change in the process parameter mean0 or lambda0, if NA simulation is perfomed without any shift: mean1, lambda1 and delta are ignored
N	the number of replicates
limit	safety parameter, stop rule for procedures with very long ARL
seed	a single value, interpreted as an integer. If specified make the simulation replicable.
w	Shiryayev-Roberts statistics used as the stopping threshold
printSummary	logical, if TRUE print a summary of the Shiryayev-Roberts ARL, PFA and CED

Value

a list with elements:

rls	a numeric vector representing the Run Length of the simulation
statistics	a numeric vector with summary statistics
run	a list of length N elements each of which has single numeric elements violationLower, violationUpper and rl

Author(s)

Daniele Amberti

References

Kenett, R., Zacks, S. with contributions by Amberti, D. *Modern Industrial Statistics: with applications in R, MINITAB and JMP*. Wiley.

Examples

```
shroArlPfaCedNorm(mean0=10,
                  sd=3,
                  n=5,
                  delta=0.5,
                  tau=10,
                  w=99,
                  seed=123)

shroArlPfaCedPois(lambda0=5,
                  delta=0.5,
                  tau=10,
                  w=99,
                  seed=123)

shroArlPfaCedNorm(mean0=15,
                  sd=3,
                  n=5,
                  delta=0.5,
                  tau=NA,
                  w=99,
                  seed=123)
```

---

simOAB   *Bayesian One-Armed Bernoulli Bandits process*

Description

Simulate the expected number of trials on arm B before switching to the known arm A, and the expected reward.

Usage

```
simOAB(N, p, al, k, gam, Ns)
```

Arguments

N	number of trials.
p	the probability of reward on arm B (unknown).
al	the known probability of reward on arm A.
k	the initial sample size on arm B.
gam	Bayesian confidence level.
Ns	number of runs in the simulation.

Value

MeanValueStoppingTime
> mean value at the stopping time

StandardDeviationST
> standard deviation of the value at the stopping time

MeanValueExpectedReward
> mean value of the expected reward

StandardDeviationST
> standard deviation of the expected reward

Author(s)

Shelemyahu Zacks

See Also

[dynOAB](#)

Examples

```
set.seed(123)
simOAB(N = 50, p = 0.6, al = 0.5, k = 10, gam = 0.95, Ns = 1000)
```

---

simulationGroup	*Simulation Group*

Description

Add a column named group to an object of class "mistatSimulation".

Usage

```
simulationGroup(x, n)
```

Arguments

x   an object of class "mistatSimulation"

n   size of the group or sample

Value

Add a column named group to an object of class "mistatSimulation".

Author(s)

Daniele Amberti

See Also

pistonSimulation, powerCircuitSimulation

Examples

```
simulationGroup(pistonSimulation(each=20), 5)
simulationGroup(powerCircuitSimulation(each=20), 5)
```

SOCELL   *Short Circuit Current of Solar Cells*

Description

Short circuit current (ISC) of 16 solar cells measured at three time epochs, one month apart.

Usage

```
data(SOCELL)
```

Format

A data frame with 16 observations on the following 3 variables.

t1 ISC at time epoch 1, a numeric vector

t2 ISC at time epoch 2, a numeric vector

t3 ISC at time epoch 3, a numeric vector

Details

Telecommunication sattelites are powered while in orbit by solar cells. Tadicell, a solar cells producer that supplies several satellite manufacturers, was requested to provide data on the degradation of its solar cells over time. Tadicell engineers performed a simulated experiment in which solar cells were subjected to temperature and illumination changes similar to those in orbit and measured the short circuit current ISC (ampers), of solar cells at three different time periods, in order to determine their rate of degradation.

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(SOCELL)

LmISC <- lm(t2 ~ 1 + t1,
            data=SOCELL)

summary(LmISC)
```

SOLDEF   *Solder Defects*

Description

Solder defects on 380 printed circuits boards of varying size.

Usage

```
data(SOLDEF)
```

Details

In SOLDEF we present results of testing batches of circuit boards for defects in solder points, after wave solderings. The batches includes boards of similar design. There were close to 1,000 solder points on each board. The results Xtare number of defects per 10^6 points *(PPM)*. The quality standard is $\lambda_0 = 100(PPM)$. λ_t values below λ_0 represent high quality soldering. In this data file there are N = 380 test results. Only 78 batches had an X_t value greater than $\lambda_0 = 100$.

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(SOLDEF)

hist(SOLDEF)
```

STEELROD   *50 Measurements of the Length of Steel Rods in* cm

---

Description

Steel rods are used in the car and truck industry to strengthen vehicle structures. Steel rods supplied by Urdon Industries are produced by a process adjusted to obtain rods of length 20 cm. However, due to natural fluctuations in the production process, the actual length of the rods varies around the nominal value of 20 cm.

Usage

```
data(STEELROD)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(STEELROD)

plot(STEELROD,
     ylab = "Steel rod Length",
     xlab = "Index")
```

STRESS   *Stress Levels*

Description

Results of a 33 factorial experiment to investigate the effects of three factors A, B, C on the stress levels of a membrane Y. The first three columns of the data provide the levels of the three factors, and column 4 presents the stress values.

Usage

```
data(STRESS)
```

Format

A data frame with 27 observations on the following 4 variables.

A levels of factor A, a numeric vector

B levels of factor B, a numeric vector

C levels of factor C, a numeric vector

stress stress levels of a membrane Y, a numeric vector

Source

Oikawa and Oka (1987)

Examples

```
data(STRESS)

summary(
  aov(stress ~ (A+B+C)^3 +I(A^2)+I(B^2)+I(C^2),
      data=STRESS))
```

SYSTEMFAILURE   *SYSTEMFAILURE*

Description

208 observations on systems operating at 90 geographically dispersed sites.

Usage

```
data("SYSTEMFAILURE")
```

Format

A data frame with 208 observations on the following 5 variables.

CustomerNumber a factor, customer ID

Censor a numeric vector

TimeStamp a numeric vector

SystemMaturity a factor with levels Mature Young

Country a factor with levels AUSTRALIA AUSTRIA BELGIUM BRAZIL BULGARIA CANADA CHINA DENMARK
    FINLAND GERMANY HUNGARY INDIA ITALY JAPAN NETHERLANDS NEW ZEALAND POLAND PORTUGAL
    REPUBLIC OF KOREA ROMANIA RUSSIAN FEDERATION SOUTH AFRICA SPAIN SWITZERLAND TURKEY
    UNITED KINGDOM UNITED STATES

Details

Twelve systems are new installed and are labeled as 'Young'. All the other systems are labeled
'Mature'. Out of the 208 observations, 68 report time stamps of a failure (uncensored). The other
observations are censored, as indicated by the value 1 in the Censor variable column. A measure
of time, the time stamp, is recorded for each observation in the data. This variable presented in
operational units (activity time), at time of observation. The bigger the time, the longer the system
performed. The observations with a value 0 of the Censor variable, represent length of operation
till failure of the systems.

Examples

```
data(SYSTEMFAILURE)
summary(subset(SYSTEMFAILURE, subset = Censor == 0, select = "TimeStamp"))
```

THICKDIFF *Difference in Thickness*

Description

Difference between the thickness of the grown silicon layer and its target value.

Usage

```
data(THICKDIFF)
```

Source

E. Yashchin (1991)

Examples

```
data(THICKDIFF)

plot(THICKDIFF, type="b")
```

toeplitz *Toeplitz matrix*

Description

partial lag correlation Toeplitz matrix.

Usage

```
toeplitz(a)
```

Arguments

a   An array containing the estimated acf from function `acf`.

Value

a matrix.

Author(s)

Shelemyahu Zacks

Examples

```
toeplitz(acf(nottem, 5)$acf)
```

TSQ $\qquad$ *T^2 values of PLACE data*

Description

368 T^2 values corresponding to the vectors (x, y, θ) of displacements (position errors) of electronic components on printed circuit boards.

Usage

```
data(TSQ)
```

Source

See PLACE

Examples

```
data(TSQ)

plot(TSQ, type="b")
```

VENDOR $\qquad$ *Number of cycles required until latch failure*

Description

Number of cycles reqiored until latch failure in 30 floppy disk drives from three different disk vendors.

Usage

```
data(VENDOR)
```

Format

A data frame with 10 observations on the following 3 variables.

vendor1 number of cycles required until latch failure for vendor A_1, a numeric vector

vendor2 number of cycles required until latch failure for vendor A_2, a numeric vector

vendor3 number of cycles required until latch failure for vendor A_3, a numeric vector

Details

Three different vendors are considered for supplying cases for floppy disk drives. The question is whether the latch mechanism that opens and closes the disk loading slot is sufficiently reliable. In order to test the reliability of this latch, three independent samples of cases, each of size $n = 10$, were randomly selected from the production lots of these vendors. The testing was performed on a special apparatus that opens and closes a latch, until it breaks. The number of cycles required until latch failure was recorded. In order to avoid uncontrollable environmental factors to bias the results, the order of testing of cases of different vendors was completely randomized. In data VENDOR there are the results of this experiment, arranged in 3 columns. Column 1 represents the sample from vendor A_1; column 2 that of vendor A_2 and column 3 of vendor A_3.

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(VENDOR)

VENDOR <- stack(VENDOR)

VENDOR$ind <- as.factor(VENDOR$ind)

VENDOR$values <- sqrt(VENDOR$values)

confint(lm(values ~ -1 + ind,
          data=VENDOR))
```

WEIBUL   *Random sample from a Weibull distribution*

Description

Values of a random sample of size $n = 50$ from a Weibull distribution.

Usage

```
data(WEIBUL)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(WEIBUL)

hist(WEIBUL)
```

YARNSTRG   *Yarn strength*

Description

Yarn strength is typically analyzed on a logarithmic scale. This logarithmic transformation produces data that is more symmetrically distributed. in YARNSTRG data there are $n = 100$ values of $Y = \ln(X)$ where X is the yarn-strength in $lb./22yarns$ of woolen fibers.

Usage

```
data(YARNSTRG)
```

Source

Kenett, R. and Zacks, S. (1998) *Modern Industrial Statistics: The Design and Control of Quality and Reliability*. Duxbury Press.

Examples

```
data(YARNSTRG)

hist(YARNSTRG,
     breaks=6,
     main="",
     xlab = "Log yarn strength")
```

Index